

## Haryana State Pollution Control Board Gurgaon North Vikas Sadan, 1st Floor, Near DC Court, Gurgaon Ph.0124-2332775 Email:- hspcbrogrn@gmail.com



## **BMW Annual Report Details**

Application Id: 37749765

Particulars of the Occupier		
Annual report submit for year:	2022	
Name of the authorized person:	Mr Mahi Tandon	
Name of HCF or CBMWTF:	C K Birla Healthcare Private Limited Brand C K Birla Hospital for Women	
Address for Correspondence:	Gurgaon	
Address of Facility:	J Block May field Garden Sector 51 Gurgaon Haryana	
Tel. No.:	9818212344	
Fax. No.:	-	
E-mail ID:	mahi.tandon@ckbhospital.com	
URL of Website:	www.ckbhospital.com	
GPS coordinates of HCF of CBMWTF:	28.424550 77.060470	
Ownership of HCF or CBMWTF:	Private	
Status of Authorization under the BMW (Mana	gementand Handing) Rules:	
Authorization No.:	BMW226UN020776551	
Valid Upto:	30/11/2025	
Status of Consents under Water Act and Air Act.:		
Valid Upto:	31/03/2025	

Health Care Facilities Details	
HCF/CBMWTF Type:	HCF
No. of Beds(for Bedded Hospital):	45
Non-Bedded Hospital (Clinic or Blood Bank or Clinical Laboratory or Research Institute or Veterinary Hospital or any other):	N.A
Licence Number:	226020776551
Licence date of expiry:	30/11/2025

Quantity of Waste Generated		
Quantity of waste generated or disposed in Kg per annum (on monthly average basis)		
Yellow Category:	14507	
Red Category:	13675	
White Category:	535	
Blue Category:	4447	
General Solid Waste:	0	

Storage, Treatment, Transportation, Processing and Disposal Facility Details

Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum:	0	
No of vehicles used for collection and transportation of BMW:	1	
Name of the Common BMW Treatment Facility Operator through which wastes are disposed of:	M/s Biotic waste management	
Details of the on-site storage facility:		
Size:	5'x8'	
Capacity:	300	
Provision of on-site storage:	NA	

Disposal Facility			
Type of Treatment Equipment	Number of Units	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annum)
List is Empty			

Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum		
Type of waste	<b>Quantity Generated</b>	Where disposal
List is Empty		

BMW Management Committee	
Do you have BMW management committee:	yes
details:	Mr Mahi Tandon ( Unit Head ) Mrs Shikha Rampal ( DGM - OPS ) Dr Isha ( infection control officer ) Ms Seema yadav ( GM Nursing ) Mr Avinash ( Sr Manager Facility ) Mr Nitesh Mishara ( AM Quality ) Mr Naresh ( DM hK ) mS jYOTI ( icn )

Training Conducted on BMW Details	
Number of training conducted on BMW Management:	7
Number of personnel trained:	84
Number of personnel trained at the time of induction:	5
Number of personnel not undergone any training so far:	0
Whether standard manual for training is available:	yes
Any other information:	NA

Details of the accident occurred	
No. of accident occurred:	0
Number of the persons affected:	0
Remedial Action taken:	0
Any Fatality occurred, details:	0

## **Other Details**

Are you meeting the standards of air Pollution from the incinerator?. How many times in last year could not met the standards?:	0
Details of Continuous online emission monitoring systems installed:	NA
Liquid waste generated and treatment methods in place. How many times you have not met the standards in a year:	0
It the disinfection method or sterilization meeting the log for standards? How many times you have not met the standards in a year?:	0
Any other relevant information:	NA